Acreage	Square Footage	Number of Parcels	Housing Status	Well status	Septic System	Septic Site Problems (Y/N)	Comment	
0.1219	5309.9640	1	Occupied Town home	Shared	Shared	Υ		
0.1636	7126.4160	3	3 Vacant	no well	partial septic		2 are vacant between parcels for sewer/water separation between 2 ~.5 ac parcels	
0.2454	10689.6240	18	Occupied	on lot and shared	known & unknown	Υ	building encroachments; septic replacement issues	
0.2781	12114.0360	1	Occupied	on lot	replaced 2022	Υ	replacement was complete excavation, removal, & replace	
0.3271	14248.4760	34	2 Vacant/32 Occupied	on lot & shared	on lot	Υ	several buildings and improvements complicate parcels; septic replacement issues	
0.3688	16064.9280	1	3 Town homes	shared	shared	Υ	Not ideal	
0.3762	16387.2720	1	Occupied	on lot	on lot	Υ	partial parking area	
0.4089	17811.6840	5	1 Vacant/4 Occupied	on lot	1 replacement 2022	Υ	maintain well spacing but not lot line or building setback	
0.4907	21374.8920	33	1 vacant/32 occupied	on lot	1 replacement 2021	Υ	maintain well spacing but not lot line or building setback	
0.5725	24938.1000	1	occupied	on lot	unknown	N	several buildings on property	
0.6542	28496.9520	4	occupied	on lot	known	Υ	building encroachments; careful consideration of adjacent parcels	
0.6600	28749.6000	1	Occupied	on lot	unknown	N	careful consideration of adjacent parcels	
0.9814	42749.7840	2	Occupied	on lot	location known	N	nearly 1 ac	cre; proper planning
Major Septic Setbacks								
All Buildings	10 feet	<u> </u>						
Well	100 feet							
"Public Well"	200 feet							
Property Lines	10 feet	<u> </u>						
it is never a good idea t	to park or drive on a septic sy	ystem						











